UNITED STATES DEPARTMENT OF THE INTERIOR

MAGI # 0437682504

10 16h

NATIONAL PARK SERVICE Washington D.C. 20240 LUD Land Application to the test to the

B - 3768

HISTORIC PRESERVATION CERTIFICATION APPLICATION—PART 1

Instructions: Applicant should read the instructions carefully before completing application. No certification may be made unless a completed application form has been received. Use typewriter or print clearly in dark ink to complete the application form. If additional space is needed to complete Part 1, use the reverse side or a separate plain sheet of paper clearly indicating the owner's name and mailing address. Part 1 of this application may be completed and sent to the appropriate State Historic Preservation Officer at anytime during the year.

PART 1 EVALUATION OF SIGNIFICA 1. Name of property: FRANKLIN SQUARE: 150		Street		
Address of property. 1518 West Fayette	e Street .			
CityBaltimore				21223
Name of historic district in which properly is located:				
	Franklin Square	HISTORIC DISC	1101	
Check here if request is for: certification (structure contributes to significance of the decentification (structure does not contribute to signification (for donation of easement on the decentification)	ficance of the district)	ervalion purposes).		
2. Description of Physical Appearance: (see instructions for map and photograph requirements-	-use reverse side il neces:	sary) '	78	
See Attached Sheets.				
3. Statement of Significance: (use revurse side if necessary)			·	
See Attached Sheets.	*			3
4. Name and Malling Address of Owner: Name Mr. Otis Warren, West Fayette Street 4300 Gelston Drive, Baltimore	The state of the s	ship	•	27
Paltimore		· vr		21220
City	**************************************	StateML	Zip Code	21223
Telephone number (during day): Area Code(301 PREPARED BY: Barbara Hoff, Dalsemer, Catzen and A I hereby altest that the information I have provided is to the bo	ssociates, inc. 121 v	Water St., Baltim	ore, MD 21202 (30))837-3691
Signature			Date 12 /	
Social Security Number or Taxpayer Identification Number				
For office use only		/.		
The structure described above is included within the boundaries the character of the district.	of a Registered Historic Di	strict and strict contrib	ules D does not con	ributeto
The structure	Register Criteria for Evalument of the Interior proced	ation (36 CFR 60 6) at Jures (36 CRF 60).	nd 🗆 will likely 🗖 w	rill not be
The structure is located in a district which \(\sigma\) appears \(\sigma\) does \(\text{N}\) will likely \(\sigma\) will not be nominated to the National Region \(\text{N}\) appears \(\sigma\) does not appear to contribute to the characteristication as substantially meeting National Register criteria.	ister in accord with Dep naracter of said district o	attrient of the Inter	rior procedures (36 C will not be recommen	CFR 60), ided for
Signature	Jui	y ac	Date /- /	1-05

HISTORIC PRESERVATION CERTIFICATION APPLICATION -- PART I

Name/address of Property: 1518 West Fayette Street,	Baltimore, MD 21223
"ame/address of Owner: Mr. Otis Warren, West Fayette L	imited Partnership
4300 Gelston Drive, Baltimore, MD 21229	Telephone: (301)945-4200
Prepared by: Barbara Hoff, Dalsemer, Catzen and Associat	es, Inc.
121 Water Street, Baltimore, MD 21202	Telephone: (301)837-3691

DESCRIPTION OF PHYSICAL APPEARANCE

This is an Italianate style rowhouse which illustrates the typical age, type, and architecture of residences within the Franklin Square Historic District. It is built of masonry and consists of a three story tall, three bay wide main building and a two story tall, two bay wide back building. The basic plan of the main and back buildings is rectangular, and they have shed roofs.

The building is constructed over a raised basement with a marble veneer and marble steps on the facade. The flat facade consists of painted, pressed brick in running bond. All of the window openings shorten at each floor level; they contain wood bullnose frames, and they had multi-light, wood, double hung sashes. The existing door is wooden, and the entry has wood frames and wood transoms. At the roofline there is a large, ornate wooden cornice which has modillions and dentils. In the mid 20th century, the facade received an application of formstone, which will be removed during the rehabilitation.

The interior consists of a typical Italianate plan with a single large room on the first floor of the main building and two rooms on the second and third floors above, as well as on both floors of the back building. Halls are located on the sides of the building, as is the staircase. Many of these spaces have been subdivided over time. The condition of the interior, prior to the required dismantling (see Part II, Project Summary), was extremely deteriorated due to lack of maintenance, aging of the materials, structural defects, and exposure to the elements.

HISTORIC PRESERVATION CERTIFICATION APPLICATION--PART I

Name/address of Property: 1518 West Fayette Street, Baltimore	MD 21223	
me/address of Owner: Mr. Otis Warren, West Fayette Limited Partne	ership	
4300 Gelston Drive, Baltimore, MD 21229	Telephone:	(301)945-4200
Prepared by: Barbara Hoff, Dalsemer, Catzen and Associates, Inc.	·	•
121 Water Street, Baltimore, MD 21202	Telephone:	(301)837-3691

STATEMENT OF SIGNIFICANCE

1518 West Fayette Street is significant to the Franklin Square Historic District because it illustrates the typical style and character of rowhouses in this residential district. The significance of the district in general lies in the quality, volume, and integrity of similar houses, which remain today as an excellent example of a mid to late 19th century neighborhood. Because the Franklin Square district was built from c.1845 to c.1875, the housing is almost exclusively Italianate, the prevailing style of residential architecture in Baltimore during those years. The distinctive characteristics of the style include flat shed roofs, large ornate cornices, vertical proportions, flat brick facades, and — among the more expensive houses — ornamentation of facade openings, raised basements with marble or brownstone veneers, three story height and three bay width. The district includes excellent examples of this rowhouse style, ranging from expensive high style designs built around Franklin Square park, to inexpensive, vernacular structures built along the alleys.

The district grew as one of Baltimore's first suburbs. Nineteenth century suburbinazation of the city began in response to a number of changes taking place simultaneously within the city: the rapid industrialization and commercialization of the heretofore residential city center, the influx of immigrants seeking inexpensive housing near these new industries and businesses; the establishment of the omnibus in 1844 and the horse-drawn trolley in 1859, and the creation of suburban parks (Franklin Square was the second one, created in 1839). These events produced an undesirable living environment in the urban core, and an accessible, desirable living environment on the outskirts of the city. Those who could afford to then left the inner city for the new suburban developments.


example of the middle-class Italianate houses. The flat facade, vertical proportions, shed roof and ornamentation epitomize the distinguishing elements of this architectural style. The rowhouse lies on land which comprised a part of 30 acres in West Baltimore which Samuel and James Canby of Wilmington, Delaware purchased in the late 1830's for future housing development. In 1839 the brothers donated a square of land to the city for use as a park, which became Franklin Square, and began leasing surrounding lots to builders for construction. In 1868, Samuel Canby leased this building to John B. Redgrave, a lumber inspector, who built the present building there in 1868 for his home.

HISTORIC PRESERVATION CERTIFI	CATION APP	LICATION -	PART I -	continued.	Page 3
Name/address of Property:	1518 W	est Fayett	e Street,	Baltimore, Mar	yland 21223
				2000 01 000	B-3768

STATEMENT OF SIGNIFICANCE

This building has remained a residence under various ownerships since then. After 1930, the house was probably leased to tenants, as were almost all of the district houses due to a great influx then of poor blacks and Southern whites. Prior to the required dismantling (see Part II, Project Summary), the building still retained its original setting and location, as well as the majority of its exterior design, materials, and workmanship. Those features which have been changed on the facade will be restored during the reassembly and rehabilitation. In this way, the essential integrity of the structure will be preserved, and the building will continue to contribute to the character of the Franklin Square Historic District.







B-3768 1518 W. Fayette Street Block 181 Lot 025 Baltimore City Baltimore West Quad.

